



Pipeline Infrastructure Limited

# Integrity Assessment of Non-Piggable Pipelines

*Divakar Kunapareddy & Kokila Shah*

28<sup>th</sup> June 2024



# Speakers Profile



**Divakar Kunapareddy**  
PIL

Head – Field O&M  
Vice President - Pipeline Infrastructure Limited (PIL)  
B.E. – Mechanical, MBA (Marketing)

Started his career with IFFCO followed by GAIL, Reliance and PIL. In his tenure of 30+ years of experience in Oil & Gas sector, he has been involved in Construction, Commissioning and Operation & Maintenance of cross-country pipelines and has formalized many innovative measures to safeguard the integrity of pipeline assets.



**Kokila Shah**  
PIL

Lead Cathodic Protection  
General Manager - Pipeline Infrastructure Limited (PIL).  
B.E. – Electrical

Started her career with Mahanagar Gas Ltd followed by PIL. She has an experience of 15 Years in Cathodic Protection and Pipeline Integrity of Natural Gas Pipelines

# Content

**01**

Introduction to  
integrity  
assessment of non  
piggable pipelines

**02**

PIL Asset  
information

**03**

Pre-assessment  
details

**04**

In-direct inspection  
details

**05**

Direct Assessment  
details

**06**

Case study –  
Spurline in Andhra  
Pradesh

**07**

Case Study –  
Spurline in  
Maharashtra

**08**

Results &  
Conclusions


**09**

Way Forward


# INTEGRITY ASSESSMENT OF NON-PIGGABLE PIPELINES

Done through ECDA / ICDA and SCCDA

ECDA / ICDA / SCCDA takes into account the threats of external corrosion, internal corrosion and Stress corrosion cracking.



# PIL Asset information – ECDA / ICDA / SCCDA carried out



# Pre-Assessment (PrA)

## ECDA:

NACE SP 0502

Data collection & review related to

- (a) Pipeline operating parameters
- (b) Soil Data
- (c) Identification of HCAs
- (d) Assessment of ECDA feasibility
- (e) All construction data , pipeline commissioning reports, historical CP trends, etc

## ICDA:


NACE – WG ICDA standard

Parameters reviewed:

- (a) Product temperature
- (b) Product Pressure
- (c) Gas composition
- (d) Flow rate
- (e) Gas Density
- (f) Elevation profiles

## SCCDA:

NACE SP 0204 and ASME B 31.8S



Apart from above, PrA for SCCDA shall also consider history of failures due to SCC, specific pipe manufacturers type, presence of disbonded coating, corrosion deposits on pipeline etc

# In-direct Inspection

## For ECDA / SCCDA

As a minimum requirement, 2 tools are selected. Vendor performed 6 surveys in tandem:

- (a) DCVG
- (b) ACVG
- (c) CAT
- (d) CIPL
- (e) Soil / Terrain Survey
- (f) Soil resistivity Survey

## For ICDA

Corrosion modelling and flow modelling done considering different scenarios of flow rate, moisture composition




Figure 50: Calculated cumulative % wall loss along with probable DEx assessment sites





# Detailed Examination (DEx)

DEx locations are identified based upon the results of ECDA , SCCDA and ICDA IDi.

Tests performed:

- (a) Ultrasonic testing for internal corrosion mapping
- (b) Magnetic Particle Inspection (MPI)
- (c) Peel Test
- (d) Surface roughness test
- (e) Patch coatings are tested
- (f) Soil measurements – pH

Post DEx cold wrap tape is applied & holiday test is done before backfilling.



Repair






# Case Study 1: Spurline in Andhra Pradesh

## IDI FINDINGS - ECDA


Basic Features: 10.75" OD, 10 Kms length, commissioned in 2009



Anomalies were flagged off and summarized post the IDi as below:

Item	Number	Comments / Conditions
Geotechnical anomalous areas	1	DOC < 1 m
Quantitative coating indications (DCVG & ACVG)	0	No flagged indications
Qualitative coating indications (ACCA)	62	Severe. ACCA used for severity prioritization of all IDi surveys conducted together
CP criteria (UP)	92	Instant off PSP < -0.85
CP criteria (OP)	199	Instant off PSP > -1.2 V

24 h data logging was carried out and AC PSP was seen to be reaching a maximum of 18 V during night time



AC current density was also calculated & found to be in the range of 1296 A/m<sup>2</sup>

# Case Study 1 : Spurline in Andhra Pradesh

## IDI FINDINGS - SCCDA


Soil augers + Carbonate testing done




Soil sampling – pH, TDS, sulphide , Soil temp, chlorides, sulphates , %moisture, carbonates

Also due to the absence of flow, low susceptibility seen for SCC

## IDI FINDINGS - ICDA



Calculated consolidated corrosion rates for the subject Line



Calculated consolidated % wall loss for the subject Line

# Case Study 1: Spurline in Andhra Pradesh

## Detailed Examination Findings:




Historical coating patch



No corrosion deposits below the patch



Peel test success on HSS



Peel test fail on 3LPE



Adhered epoxy found on pipe substrate.

## Probable Causes of Coating Disbondment:

- Epoxy thickness was seen to be 179  $\mu\text{m}$ . ISO 2808e specifies 200  $\mu\text{m}$
- Instant OFF PSP  $> -1.2$  V at certain points
- High AC PSP seen at some points which can lead to coating becoming electrically charged and break down leading to formation of bubbles causing disbondment
- Soil has alternate drying & wetting properties which can accelerate disbondment

## Results & Conclusions

- No metal loss anomalies recorded.
- No stress corrosion cracks found
- $P_{\text{safe}}$  calculations done using assumed IC threat simulations (WCS max depth of 0.64mm).
- This  $P_{\text{safe}} > \text{PIL Design pressure}$
- Can continue operations in "as is" conditions
- Remaining life – 16 years (Design – 30 years)
- Re-assessment interval – 8-10 years

# Case Study 2: Spurline in Maharashtra

Basic Features: 30.75" OD, 0.757 Kms length, commissioned in 2009



## IDI FINDINGS - ECDA

Anomalies were flagged off and summarized post the IDi as below:

Item	Number	Comments / Conditions
Geotechnical anomalous areas	2	DOC < 1 m
Quantitative coating indications (DCVG & ACVG)	0	No flagged indications
Qualitative coating indications (ACCA)	4	Severe. ACCA used for severity prioritization of all IDi surveys conducted together
CP criteria (UP)	0	Instant off PSP < -0.85
CP criteria (OP)	0	Instant off PSP > -1.2 V



- AC PSP within limit. Max. current density 35 A/m<sup>2</sup> (Corrosion unpredictable)
- No foreign pipeline interference seen
- Coating documented was 3LPE and on excavation was seen to be HSS




# Case Study 2: Spurline in Maharashtra

## IDI FINDINGS - ICDA

## IDI FINDINGS - SCCDA



Calculated consolidated corrosion rates for the subject Line



Calculated consolidated % wall loss for the subject Line



# Case Study 2: Spurline in Maharashtra



Peel test – disbondment



MPI – No signs of SCC



Deposits of FeO/OH and CaCO<sub>3</sub>

## Major findings - DEx

- (a) Coating system applied- HSS (100% disbondment)
- (b) External corrosion metal loss featured at both sites – 1 isolated pit at one site, 3 external corrosion anomalies.
- (c) Active AC corrosion phenomena

## Probable Causes for Disbondment

- (a) Instant Off  $> -1.0$  V with thin or no epoxy layer for 14 years

## Results & Conclusions

- (a) Pressure burst calculations done as per ASME B 31G, ASME B 31G modified
- (b) For all scenarios,  $P_{safe} > \text{PIL Design pressure}$
- (c) Max External Pit depth – 1mm
- (d) Simulated max. IC PD – 1.58 mm
- (e) For calculation of remaining life, max non-leaking flaw dimensions to be considered.
- (f) RL – 9.61 years
- (g) Re-assessment interval 4.8 years

# Results & Discussions

## The four main causes of coating disbondment are:

**i)** Insufficient surface anchor profile/surface roughness, prior to epoxy application. The epoxy thickness could not be measured at most of the locations as it was not adhered to the pipe. Epoxy thickness in the milling process could be a factor related to coating disbondment.

**(ii)** Cathodic disbondment due to overprotection voltages from the CP system. NACE SP0169 specifies the limits of overprotection as Instant Off PSP  $> -1.2$  V. Higher voltages can increase susceptibility of Coating Disbondment. The documented CP instant off also exceeds the NACE overprotection criterion at some locations for few of the spurlines during the Indirect Inspection (IDi) step and coating disbondment also documented in Direct Inspection DEx (DEx) step.

**(iii)** High induced AC voltages on the pipeline can also cause the coating to become electrically charged and break down, leading to formation of bubbles or voids which can eventually cause disbondment.

**(iv)** Based on the drainage properties of the soils at all the excavated locations, the soils are subject to alternate wetting and drying conditions, which can enhance coating disbondment over time.

# Conclusions

- The integrity assessment conducted for all ten (10) pipelines were deemed validated for all three (3) time-dependent threats of internal corrosion, external corrosion and stress corrosion cracking
- Phenomenon of AC interference was found to be active in **5** pipelines
- Phenomenon of coating disbondment off the pipe substrate was found to be active in all the **10** inspected pipelines
- External corrosion-based metal loss with maximum of **10% (Pit depth of 1 mm)** has been documented in **1** out of the **10** pipelines
- Internal corrosion threat for the entire system is deemed to be low – considering the natural gas quality and operating parameters remain the same (in addition to having internal coating)
- The soil, terrain and environment for all ten (10) pipelines was documented to be susceptible to environmentally assisted stress corrosion cracking (ea-SCC). But no SCC was detected at all locations inspected.

# Action Points for PIL – Way Forward

- ❖ DEx has been completed at almost all pending locations in 2024.
- ❖ XLI shall be done at critical locations going forward
- ❖ Foreign Pipeline Interference survey at identified locations
- ❖ AC interference mitigation being completed on priority at identified locations of active AC phenomena
- ❖ Software modelling to be done at AC prone areas
- ❖ Maintain instant OFF PSP in the range of -1.1 V DC for spurline in AP and -1.0 V for spurline in Maharashtra considering minimum PSP requirements also.



